

Luk W3
R= 200,00
q(g)= 4,5322
L= 1,92
T= 6,96
B= 0,12
K(N)= 5682459,31
K(E)= 6498422,84
I= 4,00%

Luk W8
R= 200,00
q(g)= 2,2008
L= 16,34
T= 8,17
B= 0,17
K(N)= 5682400,92
K(E)= 6498414,49
I= 4,00%

Luk X = 5682456,26 y = 6498403,34
K(K) 0+549,54
S(K X = 5682456,34 y = 6498422,72
S(K X = 5682453,23 y = 6498422,72
S(K X = 5682453,31 y = 6498422,85
S(K X = 5682452,92 y = 6498422,85
PLK X = 5682452,92 PLK 0+614,61

Luk X = 5682402,01 y = 6498415,65
K(K) 0+570,77
S(K X = 5682400,95 y = 6498414,33
S(K X = 5682403,92 y = 6498415,60
S(K X = 5682403,92 y = 6498415,60
PLK X = 5682390,95 y = 6498412,88
PLK 0+554,43

Luk X = 5682351,11 y = 6498403,16
K(K) 0+511,52
S(K X = 5682342,33 y = 6498400,88
S(K X = 5682342,33 y = 6498401,14
S(K X = 5682342,33 y = 6498402,44
PLK X = 5682335,69 y = 6498398,01
PLK 0+493,37

Luk W6
R= 500,00
q(g)= 2,6514
L= 20,87
T= 10,44
B= 0,11
K(N)= 5682304,66
K(E)= 6498387,64
I= 4,00%

Luk X = 5682314,48 y = 6498391,17
K(K) 0+472,95
S(K X = 5682304,63 y = 6498387,14
S(K X = 5682307,66 y = 6498387,64
S(K X = 5682307,66 y = 6498387,64
PLK X = 5682304,10 y = 6498384,53
PLK 0+452,08

Luk X = 5682271,24 y = 6498383,90
K(K) 0+375,72
S(K X = 5682270,75 y = 6498383,90
S(K X = 5682270,75 y = 6498383,90
PLK X = 5682270,75 y = 6498383,90
PLK 0+375,72

Luk X = 5682193,10 y = 6498353,37
K(K) 0+351,45
S(K X = 5682186,21 y = 6498357,02
S(K X = 5682186,21 y = 6498357,02
S(K X = 5682186,21 y = 6498357,02
PLK X = 5682186,21 y = 6498357,02
PLK 0+329,59

Luk W4
R= 300,00
q(g)= 1,8916
L= 72,86
T= 11,44
B= 0,22
K(N)= 5682186,16
K(E)= 6498351,23
I= 4,00%

Luk X = 5682142,69 y = 6498344,48
K(K) 0+294,72
S(K X = 5682134,4 y = 6498341,99
S(K X = 5682134,4 y = 6498341,99
S(K X = 5682134,4 y = 6498341,99
PLK X = 5682134,4 y = 6498341,99
PLK 0+275,77

Luk W2
R= 500,00
q(g)= 2,4723
L= 18,95
T= 9,47
B= 0,09
K(N)= 5682133,67
K(E)= 6498341,59
I= 4,00%

Luk X = 5682062,67 y = 6498319,01
K(K) 0+201,16
S(K X = 5682043,81 y = 6498316,55
S(K X = 5682043,81 y = 6498316,55
S(K X = 5682043,81 y = 6498316,55
PLK X = 5682043,81 y = 6498316,55
PLK 0+182,83

Luk W1
R= 300,00
q(g)= 1,8996
L= 18,33
T= 9,17
B= 0,14
K(N)= 5682043,84
K(E)= 6498316,55
I= 4,00%

Luk X = 5682012,9 y = 6498306,32
K(K) 0+144,70
S(K X = 5682012,9 y = 6498306,32
S(K X = 5682012,9 y = 6498306,32
S(K X = 5682012,9 y = 6498306,32
PLK X = 5682012,9 y = 6498306,32
PLK 0+127,75

Luk X = 5681971,59 y = 6498291,22
K(K) 0+107,75
S(K X = 5681971,59 y = 6498291,22
S(K X = 5681971,59 y = 6498291,22
S(K X = 5681971,59 y = 6498291,22
PLK X = 5681971,59 y = 6498291,22
PLK 0+107,75

Luk X = 5681851,58 y = 6498270,38
K(K) 0+07,75
S(K X = 5681851,58 y = 6498270,38
S(K X = 5681851,58 y = 6498270,38
S(K X = 5681851,58 y = 6498270,38
PLK X = 5681851,58 y = 6498270,38
PLK 0+07,75